

Overall Facility Pass or Fail:
Pass



No.
00086

PFO Tank Inspection

Location

Customer	Location Name	Address
4Refuel	York1 Scarborough	300 Nugget Ave. Scarborough Ontario

Tank Information

Tank Type:	Size in Liters:	Who Owns the tank?	Any TSSA Orders?
Round	2200	Fuel Supplier	No
Secondary Containment	Serial Number:	Spill Container on tank?	Any Red Tags?
Double Wall	G32183821	Yes	No
Manufacturer	Tank Number:		
Nithwood			
	Age of Tank In Years:		
	2023		

Gasoline Tank:

Pump Information

Product Selection:	Pump Type:	Pump Speed?	120 Volt Pump Check List
Dyed Diesel	120 Volt Pump	Normal	Pump connection ok
Card lock used?	Meter Used?	Hose Size?	Hard Wire ok
No	Yes	3/4 inch	Plug end ok
		Hose length in feet?	Nozzle ok
		15	Hose ok
			Swivel ok

Overall Facility Pass or Fail:
Pass



No.
00086

Pictures

Take pictures of the tank label and the tank

Lable



Tank picture



Pump



Other Photo



Comments on additional picture:
Vacuum gauge good

Overall Facility Pass or Fail:
Pass



No.
00086

Inspection Report:

Items:	Pass/Fail/NA	Comments
Impact protection	Pass	
Venting	Pass	
Vent alarm	NA	
Vacuum on tank	Pass	
Free of leaks	Pass	
Free of rust	Pass	
Tank Gauge	NA	
Openings plugged	Pass	
Location Distances	Pass	
Electrical ok	Pass	
Spill Kit	Pass	
Fire Extinguishers	Pass	
Stable Base	Pass	
Lables Diesel/Gas	Pass	
Signage in place	Pass	
Emergency Procedures	Pass	
Piping ok	Pass	
Overfill alarm	Pass	
Dyke dry	Pass	
Hose	Pass	
Nozzle	Pass	
Swivel	NA	

Summary

Overall Facility Pass or Fail:
Pass

Overall Comments:

Inspector Name

Stefano Magliozzi

Certificate Number: 0731827

Petroleum Contractor: FS 000198013

Date:

06/16/2026

Signature:

A handwritten signature in black ink, appearing to be "Stefano Magliozzi", written over a white background.

Unavera Group Inc. | 416-UNAVERA | www.unaveragroup.com