

Overall Facility Pass or Fail:
Pass



No.
00046

PFO Tank Inspection

Location

Customer	Location Name	Address
4Refuel	York1	375 Gauge St. N. Hamilton Ontario

Tank Information

Tank Type: Round	Size in Liters: 4500	Who Owns the tank? Fuel Supplier	Any TSSA Orders? No
Secondary Containment Double Wall	Serial Number: G32183793	Spill Container on tank? Yes	Any Red Tags? No
Manufacturer Nithwood	Tank Number:		
	Age of Tank In Years: 2023		

Gasoline Tank:

Pump Information

Product Selection: Dyed Diesel	Pump Type: 120 Volt Pump	Pump Speed? Normal	120 Volt Pump Check List Pump connection ok
Card lock used? No	Meter Used? Yes	Hose Size? 3/4 inch	Hard Wire ok
		Hose length in feet? 15	Plug end ok
			Nozzle ok
			Hose ok
			Swivel ok

Pictures

Take pictures of the tank label and the tank

Lable



Tank picture



Pump



Overall Facility Pass or Fail:
Pass



No.
00046

Inspection Report:

Items:	Pass/Fail/NA	Comments
Impact protection	Pass	
Venting	Pass	
Vent alarm	NA	
Vacuum on tank	Pass	
Free of leaks	Pass	
Free of rust	Pass	
Tank Gauge	Pass	
Openings plugged	Pass	
Location Distances	Pass	
Electrical ok	Pass	
Spill Kit	Pass	
Fire Extinguishers	Pass	
Stable Base	Pass	
Lables Diesel/Gas	Pass	
Signage in place	Pass	
Emergency Procedures	Pass	
Piping ok	Pass	
Overfill alarm	NA	
Dyke dry	Pass	
Hose	Pass	
Nozzle	Pass	
Swivel	Pass	

Summary

Overall Facility Pass or Fail:
Pass

Overall Comments:

Inspector Name
Stefano Magliozzi
Certificate Number: 0731827
Petroleum Contractor: FS 000198013

Date:
03/20/2024

Signature: