

Overall Facility Pass or Fail:  
Pass



No.  
00047

### PFO Tank Inspection

#### Location

Customer	Location Name	Address
4Refuel	York1	375 Gauge St. N. Hamilton Ontario

#### Tank Information

<b>Tank Type:</b> Round	<b>Size in Liters:</b> 4500	<b>Who Owns the tank?</b> Fuel Supplier	<b>Any TSSA Orders?</b> No
<b>Secondary Containment</b> Double Wall	<b>Serial Number:</b> G32183741	<b>Spill Container on tank?</b> Yes	<b>Any Red Tags?</b> No
<b>Manufacturer</b> Nithwood	<b>Tank Number:</b>		
	<b>Age of Tank In Years:</b> 2023		

Gasoline Tank:

#### Pump Information

<b>Product Selection:</b> Clear Diesel	<b>Pump Type:</b> 120 Volt Pump	<b>Pump Speed?</b> Normal	<b>120 Volt Pump Check List</b> Pump connection ok
<b>Card lock used?</b> No	<b>Meter Used?</b> Yes	<b>Hose Size?</b> 3/4 inch	Hard Wire ok
		<b>Hose length in feet?</b> 15	Plug end ok
			Nozzle ok
			Hose ok

Pictures

Take pictures of the tank label and the tank

Lable



Tank picture



Pump



Overall Facility Pass or Fail:  
Pass



No.  
00047

**Inspection Report:**

Items:	Pass/Fail/NA	Comments
Impact protection	Pass	
Venting	Pass	
Vent alarm	NA	
Vacuum on tank	Pass	
Free of leaks	Pass	
Free of rust	Pass	
Tank Gauge	Pass	
Openings plugged	Pass	
Location Distances	Pass	
Electrical ok	Pass	
Spill Kit	Pass	
Fire Extinguishers	Pass	
Stable Base	Pass	
Lables Diesel/Gas	Pass	
Signage in place	Pass	
Emergency Procedures	Pass	
Piping ok	Pass	
Overfill alarm	NA	
Dyke dry	Pass	
Hose	Pass	
Nozzle	Pass	
Swivel	NA	

**Summary**

Overall Facility Pass or Fail:  
Pass

Overall Comments:

Inspector Name  
Stefano Magliozzi  
Certificate Number: 0731827  
Petroleum Contractor: FS 000198013

Date:  
03/20/2024

Signature: