

Overall Facility Pass or Fail:
Pass



No.
00090

PFO Tank Inspection

Location

Customer	Location Name	Address
4Refuel	York1	375 Gauge St. N. Hamilton Ontario

Tank Information

Tank Type:	Size in Liters:	Who Owns the tank?	Any TSSA Orders?
Round	4500	Fuel Supplier	No
Secondary Containment	Serial Number:	Spill Container on tank?	Any Red Tags?
Double Wall	G32183793	Yes	No
Manufacturer	Tank Number:		
Nithwood			
	Age of Tank In Years:		
	2023		

Gasoline Tank:

Pump Information

Product Selection:	Pump Type:	Pump Speed?	120 Volt Pump Check List
Dyed Diesel	120 Volt Pump	Normal	Pump connection ok
Card lock used?	Meter Used?	Hose Size?	Hard Wire ok
No	Yes	3/4 inch	Plug end ok
		Hose length in feet?	Nozzle ok
		15	Hose ok
			Swivel ok



UNAVERA
GROUP INC
Environmental Contractors

No.
00090

Pictures

Take pictures of the tank label and the tank


Lable



Tank picture



Pump



Overall Facility Pass or Fail:
Pass



No.
00090

Inspection Report:

Items:	Pass/Fail/NA	Comments
Impact protection	Pass	
Venting	Pass	
Vent alarm	NA	
Vacuum on tank	Pass	
Free of leaks	Pass	
Free of rust	Pass	
Tank Gauge	Pass	
Openings plugged	Pass	
Location Distances	Pass	
Electrical ok	Pass	
Spill Kit	Pass	
Fire Extinguishers	Pass	
Stable Base	Pass	
Lables Diesel/Gas	Pass	
Signage in place	Pass	
Emergency Procedures	Pass	
Piping ok	Pass	
Overfill alarm	NA	
Dyke dry	Pass	
Hose	Pass	
Nozzle	Pass	
Swivel	Pass	

Summary

Overall Facility Pass or Fail:
Pass

Overall Comments:

Inspector Name

Stefano Magliozzi

Certificate Number: 0731827

Petroleum Contractor: FS 000198013

Date:

06/16/2025

Signature:

Unavera Group Inc. | 416-UNAVERA | www.unaveragroup.com