Overall Facility Pass or Fail:
Pass

No.
00094

PFO Tank Inspection

Location

Customer
4Refuel

Location Name
York 1 Waste

Address
195 Bethridge Rd.
Etobicoke
Ontario

Tank Information

Tank Type:
Round

Size in Liters:
2200

Who Owns the tank?
Fuel Supplier

Any TSSA Orders?
No

Secondary Containment
Double Wall

Serial Number:
D66194929

Spill Container on tank?
Yes

Any Red Tags?
No

Manufacturer
Nithwood

Tank Number:

Age of Tank In Years:
2019

Gasoline Tank:

Pump Information

Product Selection:
Dyed Diesel

Pump Type:
120 Volt Pump

Pump Speed?
Normal

120 Volt Pump Check List
Pump connection ok
Hard Wire ok
Plug end ok
Nozzle ok
Hose ok
Swivel ok

Card lock used?
No

Meter Used?
Yes

Hose Size?
1 inch

Hose length in feet?
30

Overall Facility Pass or Fail:
Pass


UNAVERA GROUP INC
Environmental Contractors

No.
00094

Pictures

Take pictures of the tank label and the tank


Lable



Tank picture



Pump



Other Photo



Comments on additional picture:
Vacuum Gauge

Overall Facility Pass or Fail:
Pass

UNAVERA GROUP INC
Environmental Contractors

No.
00094

Inspection Report:

Items:	Pass/Fail/NA	Comments
Impact protection	Pass	
Venting	Pass	
Vent alarm	Pass	
Vacuum on tank	Pass	
Free of leaks	Pass	
Free of rust	Pass	
Tank Gauge	Pass	
Openings plugged	Pass	
Location Distances	Pass	
Electrical ok	Pass	
Spill Kit	Pass	
Fire Extinguishers	Pass	
Stable Base	Pass	
Lables Diesel/Gas	Pass	
Signage in place	Pass	
Emergency Procedures	Pass	
Piping ok	Pass	
Overfill alarm	Pass	
Dyke dry	Pass	
Hose	Pass	
Nozzle	Pass	
Swivel	Pass	

Summary

Overall Facility Pass or Fail:
Pass

Overall Comments:

Inspector Name
Stefano Magliozzi
Certificate Number: 0731827
Petroleum Contractor: FS 000198013

Date:
08/24/2026

Signature:

