

Overall Facility Pass or Fail:  
Pass



No.  
00089

### PFO Tank Inspection

#### Location

|                 |                      |                                      |
|-----------------|----------------------|--------------------------------------|
| <b>Customer</b> | <b>Location Name</b> | <b>Address</b>                       |
| 4Refuel         | York1 Whitby         | 113 Warren Road<br>Whitby<br>Ontario |

#### Tank Information

|                              |                              |                                 |                         |
|------------------------------|------------------------------|---------------------------------|-------------------------|
| <b>Tank Type:</b>            | <b>Size in Liters:</b>       | <b>Who Owns the tank?</b>       | <b>Any TSSA Orders?</b> |
| Round                        | 4500                         | Fuel Supplier                   | No                      |
| <b>Secondary Containment</b> | <b>Serial Number:</b>        | <b>Spill Container on tank?</b> | <b>Any Red Tags?</b>    |
| Double Wall                  | G32183740                    | Yes                             | No                      |
| <b>Manufacturer</b>          | <b>Tank Number:</b>          |                                 |                         |
| Nithwood                     |                              |                                 |                         |
|                              | <b>Age of Tank In Years:</b> |                                 |                         |
|                              | 2023                         |                                 |                         |

Gasoline Tank:

#### Pump Information

|                           |                    |                             |                                 |
|---------------------------|--------------------|-----------------------------|---------------------------------|
| <b>Product Selection:</b> | <b>Pump Type:</b>  | <b>Pump Speed?</b>          | <b>120 Volt Pump Check List</b> |
| Clear Diesel              | 120 Volt Pump      | Normal                      | Pump connection ok              |
| <b>Card lock used?</b>    | <b>Meter Used?</b> | <b>Hose Size?</b>           | Hard Wire ok                    |
| No                        | Yes                | 3/4 inch                    | Plug end ok                     |
|                           |                    | <b>Hose length in feet?</b> | Nozzle ok                       |
|                           |                    | 15                          | Hose ok                         |
|                           |                    |                             | Swivel ok                       |

Overall Facility Pass or Fail:  
Pass



No.  
00089

## Pictures

Take pictures of the tank label and the tank

Lable



Tank picture



Pump



Overall Facility Pass or Fail:  
Pass



No.  
00089

### Inspection Report:

| Items:               | Pass/Fail/NA | Comments |
|----------------------|--------------|----------|
| Impact protection    | Pass         |          |
| Venting              | Pass         |          |
| Vent alarm           | NA           |          |
| Vacuum on tank       | Pass         |          |
| Free of leaks        | Pass         |          |
| Free of rust         | Pass         |          |
| Tank Gauge           | NA           |          |
| Openings plugged     | Pass         |          |
| Location Distances   | Pass         |          |
| Electrical ok        | Pass         |          |
| Spill Kit            | Pass         |          |
| Fire Extinguishers   | Pass         |          |
| Stable Base          | Pass         |          |
| Lables Diesel/Gas    | Pass         |          |
| Signage in place     | Pass         |          |
| Emergency Procedures | Pass         |          |
| Piping ok            | Pass         |          |
| Overfill alarm       | Pass         |          |
| Dyke dry             | Pass         |          |
| Hose                 | Pass         |          |
| Nozzle               | Pass         |          |
| Swivel               | NA           |          |

### Summary

Overall Facility Pass or Fail:  
Pass

Overall Comments:

Inspector Name

Stefano Magliozzi

Certificate Number: 0731827

Petroleum Contractor: FS 000198013

Date:

06/16/2026

Signature:

A handwritten signature in black ink, appearing to be "Stefano Magliozzi", written over a white background.

Unavera Group Inc. | 416-UNAVERA | [www.unaveragroup.com](http://www.unaveragroup.com)